



CN2

PIN	Signal
5	A
4	/A
7	B
9	/B
10	Z
2	/Z
14.16	+5V
13.15	GND

CN1-A

PIN	Signal	Function	Label
42	V-REF	Speed Mode DC10V +	A+
13	GND	Speed Mode DC10V -	A-

CN1-B

PIN	Signal	Param	Function	Label
17	VDD		Internal DC24V	24N
11	COM+		Connect to VDD	
45,47,49	COM-			0N
9	DI1 (SDN)	P2-10=101	Servo Ready (NO)	76
10	DI2 (SPDLM)	P2-11=104	Speed Limited (NO)	73
34	DI3 (STF)	P2-12=116	Spin CW (NO)	72
8	DI4 (STB)	P2-13=117	Spin CCW (NO)	74
33	DI5 (ARST)	P2-14=102	Reset Driver (NO)	71
30	DI8 (EMGS)	P2-17=21	CNC Alarm (NC)	75
7	DO1+ (SRDY)	P2-18=101	Servo Ready (NO)	141
6	DO1-		Connect to COM-	
5	DO2+ (ZSPD)	P2-19=103	Zero Speed (NO)	142
4	DO2-		Connect to COM-	
3	DO3+ (TSPD)	P2-20=109	Target Speed (NO)	143
2	DO3-		Connect to COM-	
28	DO5+ (ALRM)	P2-22=7	Driver Alarm (NC)	144
27	DO5-		Connect to COM-	

備註

機型	
規格	
設計	日期
製圖	日期
校對	日期

光鉛企業股份有限公司
KEEN CHIEF CO., LTD.

圖名	
圖號	